

Name:	Additional Trail 17
Reference No.:	61
Length (m):	276.40
Average Width (m):	1
Condition:	Poor
Level of Usage:	Medium
Predominant Usage Type:	Running/Walking
Potential to Harm Heritage or Environmental Features:	Harm observed
Required by City:	-
Recommendation:	Close. Unauthorised entryways to trails 77 and 74. Entryway to trail 74 is close by so these trails are unnecessary. Erosion present and weeds spreading throughout the Tuart woodlands TEC.



Name:	Transmission Hill Ridgeline
Reference No.:	62
Length (m):	210.68
Average Width (m):	0.5
Condition:	Poor
Level of Usage:	Medium
Predominant Usage Type:	Running/ Walking
Potential to Harm Heritage or Environmental Features:	Harm likely
Required by City:	No
Recommendation:	Close. [REDACTED] Honeymyrtle shrublands TEC. Potential to facilitate weed spread into the surrounding environmental and heritage features. Poor condition trail not well used.




Name:	Mid 2
Reference No.:	63
Length (m):	107.49
Average Width (m):	1
Condition:	Poor
Level of Usage:	High
Predominant Usage Type:	Running/Walking
Potential to Harm Heritage or Environmental Features:	Harm likely
Required by City:	No
Recommendation:	Close. Unnecessary shortcut between trails 75 and 93. Intersects with Honeymyrtle shrublands TEC. Potential to facilitate weed spread and trampling effects into the surrounding TEC.



Name:	Snakecharmer
Reference No.:	64
Length (m):	181.69
Average Width (m):	1
Condition:	Poor
Level of Usage:	High
Predominant Usage Type:	Running/Walking
Potential to Harm Heritage or Environmental Features:	Harm observed
Required by City:	No
Recommendation:	Close. Intersects with Tuart woodlands TEC, Honeymyrtle shrublands TEC Currently facilitating weed spread and erosion to nearby environmental and heritage values. Poor condition trail.



Name:	Additional Trail 18
Reference No.:	65
Length (m):	344.63
Average Width (m):	1
Condition:	Poor
Level of Usage:	Medium
Predominant Usage Type:	Running/Walking
Potential to Harm Heritage or Environmental Features:	Harm observed
Required by City:	-
Recommendation:	Close. Unnecessary meandering trails connecting trails 21, 22, 95 and 34. Intersects with the Honeymyrtle shrublands TEC. Erosion and vegetation trampling effects currently present. Poor condition, potentially dangerous trail.



Name:	Additional Trail 19
Reference No.:	66
Length (m):	175.34
Average Width (m):	0.5
Condition:	Poor
Level of Usage:	Low
Predominant Usage Type:	Running/Walking
Potential to Harm Heritage or Environmental Features:	Harm likely
Required by City:	-
Recommendation:	Close. Unnecessary shortcut connecting trails 95, 33 and 35. Intersects with the Honeymyrtle shrubland TEC. Potential to facilitate weed spread into the surrounding TEC. Poor condition trail, overgrown with vegetation.



Name:	Road to Nowhere
Reference No.:	67
Length (m):	119.54
Average Width (m):	0.5
Condition:	Poor
Level of Usage:	Low
Predominant Usage Type:	Running/Walking
Potential to Harm Heritage or Environmental Features:	Harm likely
Required by City:	No
Recommendation:	Close. Intersects with Honeymyrtle shrubland TEC and Tuart woodland TEC. Potential to introduce weeds into the surrounding TEC patches. Poor condition trail, very overgrown. With native vegetation.



Name:	Mid
Reference No.:	68
Length (m):	26.75
Average Width (m):	0.5
Condition:	Poor
Level of Usage:	Medium
Predominant Usage Type:	Mixed Use
Potential to Harm Heritage or Environmental Features:	Harm likely
Required by City:	No
Recommendation:	Close. Unnecessary shortcut. Intersects with the Tuart woodlands TEC. Potential to introduce weeds into the surrounding TEC.



Name:	Quarry Track
Reference No.:	69
Length (m):	166.54
Average Width (m):	1
Condition:	Poor
Level of Usage:	Low
Predominant Usage Type:	Mixed Use
Potential to Harm Heritage or Environmental Features:	Harm observed
Required by City:	No
Recommendation:	Close. Unauthorised mountain bike circuit including bike jumps. Erosion, trampling and weeds present. Intersects with Honeymyrtle shrublands TEC and Tuart woodlands TEC. Overgrown vegetation in sections. Poor condition trail. Not well used. Dangerous rocky sections of trail.



Name:	Additional Trail 20
Reference No.:	70
Length (m):	26.1
Average Width (m):	0.5
Condition:	Poor
Level of Usage:	Low
Predominant Usage Type:	Running/Walking
Potential to Harm Heritage or Environmental Features:	Harm observed
Required by City:	-
Recommendation:	Close. Unnecessary shortcut connecting trails 124 and 37. Overgrown, trampling of native vegetation present. Potential to spread weeds into the adjacent Honeymyrtle shrubland TEC. Poor condition trail, not frequently used.



Name:	Additional Trail 21
Reference No.:	71
Length (m):	99.82
Average Width (m):	0.75
Condition:	Poor
Level of Usage:	Low
Predominant Usage Type:	Running/Walking
Potential to Harm Heritage or Environmental Features:	Harm likely
Required by City:	-
Recommendation:	Close. Intersects with Northern Spearwood shrublands PEC, Tuart woodlands TEC and revegetation area. Potential to spread weeds into the surrounding environmental features. Unnecessary trail connecting trails 28,45 and 105. Poor condition trail not frequently used.



Name:	Additional Trail 22
Reference No.:	72
Length (m):	79.08
Average Width (m):	3
Condition:	Poor
Level of Usage:	Low
Predominant Usage Type:	Running/Walking
Potential to Harm Heritage or Environmental Features:	Harm unlikely
Required by City:	-
Recommendation:	Close. Unnecessary trail parallel to trail 21. High weed load along trail and erosion present.



Name:	Additional Trail 23
Reference No.:	73
Length (m):	105.89
Average Width (m):	2
Condition:	Good
Level of Usage:	High
Predominant Usage Type:	Biking
Potential to Harm Heritage or Environmental Features:	Harm unlikely
Required by City:	-
Recommendation:	Keep open - formalise. Trail used as bicycle access between Spearwood Avenue and trail 1.



Name:	Firebreak 4
Reference No.:	74
Length (m):	254.78
Average Width (m):	3
Condition:	Good
Level of Usage:	High
Predominant Usage Type:	Running/Walking
Potential to Harm Heritage or Environmental Features:	Harm unlikely
Required by City:	Yes
Recommendation:	Keep open - maintenance. Trail overgrown in sections, may require minor vegetation trimming. Formalisation recommended in trampled sections.




Name:	Putins Fetish
Reference No.:	75
Length (m):	186.13
Average Width (m):	2.5
Condition:	Medium
Level of Usage:	High
Predominant Usage Type:	Running/Walking
Potential to Harm Heritage or Environmental Features:	Harm unlikely
Required by City:	No
Recommendation:	Close. High risk of harm to the environment through continued use of the trail.



Name:	South 3
Reference No.:	76
Length (m):	67.26
Average Width (m):	1
Condition:	Medium
Level of Usage:	High
Predominant Usage Type:	Running/Walking
Potential to Harm Heritage or Environmental Features:	Harm likely
Required by City:	Yes
Recommendations:	Keep open. Trail 76 is required to be kept open by the City, however [REDACTED] Fencing [REDACTED] should be installed to mitigate negative effects of foot traffic on this site by users of this section of trail 76.



Name:	Firebreak 4
Reference No.:	77
Length (m):	52.67
Average Width (m):	1
Condition:	Poor
Level of Usage:	Medium
Predominant Usage Type:	Running/ Walking
Potential to Harm Heritage or Environmental Features:	Harm Observed
Required by City:	Yes
Recommendation:	Keep open. Maintenance should be undertaken to ensure track remains useable.



Name:	North Link
Reference No.:	78
Length (m):	16.65
Average Width (m):	1
Condition:	Poor
Level of Usage:	Low
Predominant Usage Type:	Mixed Use
Potential to Harm Heritage or Environmental Features:	Harm observed
Required by City:	No
Recommendation:	Keep open. Track 78 is required to be included as part of the proposed quarry loop, and will link to track 39.



Name:	Footway 3
Reference No.:	79
Length (m):	199.1
Average Width (m):	4
Condition:	Good
Level of Usage:	High
Predominant Usage Type:	Running/Walking
Potential to Harm Heritage or Environmental Features:	Harm unlikely
Required by City:	Yes
Recommendation:	Keep open.



Name:	Firebreak
Reference No.:	80
Length (m):	206.40
Average Width (m):	4
Condition:	Good
Level of Usage:	High
Predominant Usage Type:	Running/Walking
Potential to Harm Heritage or Environmental Features:	Harm unlikely
Required by City:	Yes
Recommendation:	Keep open.

