


Name:	Footway
Reference No.:	81
Length (m):	152.65
Average Width (m):	4
Condition:	Good
Level of Usage:	High
Predominant Usage Type:	Running/Walking
Potential to Harm Heritage or Environmental Features:	Harm unlikely
Required by City:	Yes
Recommendation:	Keep open.



Name:	South- West
Reference No.:	82
Length (m):	219.47
Average Width (m):	5
Condition:	Good
Level of Usage:	High
Predominant Usage Type:	Running/Walking
Potential to Harm Heritage or Environmental Features:	Harm unlikely
Required by City:	Yes
Recommendation:	Keep open.



Name:	Manning Stairs
Reference No.:	83
Length (m):	106.63
Average Width (m):	5
Condition:	Good
Level of Usage:	High
Predominant Usage Type:	Running/Walking
Potential to Harm Heritage or Environmental Features:	Harm unlikely
Required by City:	Yes
Recommendation:	Keep open.



Name:	Manning Stairs - 1
Reference No.:	84
Length (m):	150.99
Average Width (m):	5
Condition:	Good
Level of Usage:	High
Predominant Usage Type:	Running/Walking
Potential to Harm Heritage or Environmental Features:	Harm unlikely
Required by City:	Yes
Recommendation:	Keep open.



Name:	East 2
Reference No.:	85
Length (m):	435.63
Average Width (m):	4
Condition:	Good
Level of Usage:	High
Predominant Usage Type:	Running/Walking
Potential to Harm Heritage or Environmental Features:	Harm unlikely
Required by City:	Yes
Recommendation:	Keep open.



Name:	East 2
Reference No.:	86
Length (m):	165.85
Average Width (m):	4
Condition:	Good
Level of Usage:	High
Predominant Usage Type:	Running/Walking
Potential to Harm Heritage or Environmental Features:	Harm unlikely
Required by City:	Yes
Recommendation:	Keep open.



Name:	South 2
Reference No.:	87
Length (m):	75.63
Average Width (m):	3
Condition:	Medium
Level of Usage:	High
Predominant Usage Type:	Running/Walking
Potential to Harm Heritage or Environmental Features:	Harm likely
Required by City:	No
Recommendation:	Close. [REDACTED]



Name:	Centre 1
Reference No.:	88
Length (m):	177.26
Average Width (m):	4
Condition:	Medium
Level of Usage:	High
Predominant Usage Type:	Running/Walking
Potential to Harm Heritage or Environmental Features:	Harm unlikely
Required by City:	Yes
Recommendation:	Keep open.



Name:	Mid 2
Reference No.:	89
Length (m):	45.94
Average Width (m):	4
Condition:	Medium
Level of Usage:	High
Predominant Usage Type:	Running/Walking
Potential to Harm Heritage or Environmental Features:	Harm unlikely
Required by City:	Yes
Recommendation:	Keep open.



Name:	Backyard Track
Reference No.:	90
Length (m):	347.38
Average Width (m):	4
Condition:	Medium
Level of Usage:	High
Predominant Usage Type:	Running/Walking
Potential to Harm Heritage or Environmental Features:	Harm unlikely
Required by City:	Yes
Recommendation:	Keep open.



Name:	Additional Trail 4
Reference No.:	91
Length (m):	89.71
Average Width (m):	4
Condition:	Medium
Level of Usage:	High
Predominant Usage Type:	Running/Walking
Potential to Harm Heritage or Environmental Features:	Harm unlikely
Required by City:	-
Recommendation:	Keep open.



Name:	Centre 3
Reference No.:	92
Length (m):	70.2
Average Width (m):	2.5
Condition:	Medium
Level of Usage:	High
Predominant Usage Type:	Running/Walking
Potential to Harm Heritage or Environmental Features:	Harm unlikely
Required by City:	Yes
Recommendations:	Keep open. Undertake track maintenance.



Name:	Mid 2
Reference No.:	93
Length (m):	36.28
Average Width (m):	2.5
Condition:	Medium
Level of Usage:	High
Predominant Usage Type:	Running/Walking
Potential to Harm Heritage or Environmental Features:	Harm unlikely
Required by City:	Yes
Recommendations:	Keep open. Undertake track maintenance.



Name:	Mid 3
Reference No.:	94
Length (m):	291.26
Average Width (m):	2.5
Condition:	Medium
Level of Usage:	High
Predominant Usage Type:	Running/Walking
Potential to Harm Heritage or Environmental Features:	Harm unlikely
Required by City:	Yes
Recommendations:	Keep open. Undertake track maintenance.



Name:	Mid
Reference No.:	95
Length (m):	235.81
Average Width (m):	2
Condition:	Good
Level of Usage:	High
Predominant Usage Type:	Running/Walking
Potential to Harm Heritage or Environmental Features:	Harm unlikely
Required by City:	Yes
Recommendation:	Keep open - maintenance. Some track pruning should be undertaken if the City wishes to keep this trail open.



Name:	Mid 5
Reference No.:	96
Length (m):	50.25
Average Width (m):	2
Condition:	Good
Level of Usage:	High
Predominant Usage Type:	Running/Walking
Potential to Harm Heritage or Environmental Features:	Harm unlikely
Required by City:	Yes
Recommendation:	Keep open - maintenance. Some track pruning should be undertaken if the City wishes to keep this trail open.



Name:	Northern Most Firebreak
Reference No.:	97
Length (m):	417.22
Average Width (m):	4
Condition:	Good
Level of Usage:	High
Predominant Usage Type:	Running/Walking
Potential to Harm Heritage or Environmental Features:	Harm unlikely
Required by City:	Yes
Recommendation:	Keep open.



Name:	Mid 4
Reference No.:	98
Length (m):	147.41
Average Width (m):	4
Condition:	Good
Level of Usage:	High
Predominant Usage Type:	Running/Walking
Potential to Harm Heritage or Environmental Features:	Harm unlikely
Required by City:	Yes
Recommendation:	Keep open.



Name:	Mid 6
Reference No.:	99
Length (m):	64
Average Width (m):	4
Condition:	Good
Level of Usage:	High
Predominant Usage Type:	Running/Walking
Potential to Harm Heritage or Environmental Features:	Harm unlikely
Required by City:	Yes
Recommendation:	Keep open.



Name:	South- West
Reference No.:	100
Length (m):	82
Average Width (m):	4
Condition:	Good
Level of Usage:	High
Predominant Usage Type:	Running/Walking
Potential to Harm Heritage or Environmental Features:	Harm unlikely
Required by City:	Yes
Recommendation:	Keep open.



Name:	North 3
Reference No.:	101
Length (m):	62.29
Average Width (m):	4
Condition:	Good
Level of Usage:	High
Predominant Usage Type:	Running/Walking
Potential to Harm Heritage or Environmental Features:	Harm unlikely
Required by City:	Yes
Recommendation:	Keep open.



Name:	Firebreak 2
Reference No.:	102
Length (m):	86.81
Average Width (m):	1
Condition:	Medium
Level of Usage:	High
Predominant Usage Type:	Running/Walking
Potential to Harm Heritage or Environmental Features:	Harm likely
Required by City:	No
Recommendation:	Close. High weed load and overgrown trail. Risk of weed incursion into Honeymyrtle shrubland TEC patch. Would require significant inputs to formalise and reduce weed load, not required by the City.



Name:	Mid 7
Reference No.:	103
Length (m):	29.43
Average Width (m):	1
Condition:	Medium
Level of Usage:	High
Predominant Usage Type:	Running/Walking
Potential to Harm Heritage or Environmental Features:	Harm likely
Required by City:	Yes
Recommendation:	Close. Risk of weed spread and erosion into Tuart woodland and Honeymyrtle shrubland TECs high. Provides access to unauthorised mountain biking trails.



Name:	East
Reference No.:	104
Length (m):	17.77
Average Width (m):	1
Condition:	Medium
Level of Usage:	High
Predominant Usage Type:	Running/Walking
Potential to Harm Heritage or Environmental Features:	Harm likely
Required by City:	Yes
Recommendation:	Close. Risk of weed spread and erosion into Tuart woodland and Honeymyrtle shrubland TECs high. Provides access to unauthorised mountain biking trails.



Name:	Dan's Trail
Reference No.:	105
Length (m):	182.47
Average Width (m):	1
Condition:	Poor
Level of Usage:	High
Predominant Usage Type:	Mixed Use
Potential to Harm Heritage or Environmental Features:	Harm observed
Required by City:	No
Recommendation:	Close. Currently spreading weeds into adjacent vegetation. Risk of erosion. Intersects with Honeymyrtle shrubland TEC and Northern Spearwood shrubland PEC.



Name:	Bellbottoms
Reference No.:	106
Length (m):	80.87
Average Width (m):	0.3
Condition:	Poor
Level of Usage:	Low
Predominant Usage Type:	Running/Walking
Potential to Harm Heritage or Environmental Features:	Harm observed
Required by City:	No
Recommendation:	Close. Poor condition trail not frequently used. Vegetation trampling occurring.



Name:	South 3
Reference No.:	107
Length (m):	146.40
Average Width (m):	1
Condition:	Medium
Level of Usage:	High
Predominant Usage Type:	Running/Walking
Potential to Harm Heritage or Environmental Features:	Harm likely
Required by City:	No
Recommendation:	Close. Intersects with the Tuart woodland TEC and adjacent to the Honeymyrtle shrublands TEC. Medium condition trail with the potential to facilitate weed spread and erosion effects into environmental and heritage areas.




Name:	Brown and Sticky
Reference No.:	108
Length (m):	296.55
Average Width (m):	1
Condition:	Medium
Level of Usage:	High
Predominant Usage Type:	Running/Walking
Potential to Harm Heritage or Environmental Features:	Harm likely
Required by City:	No
Recommendation:	Close. Intersects with the Tuart woodland TEC and adjacent to the Honeymyrtle shrublands TEC. Medium condition trail with the potential to facilitate weed spread and erosion effects into environmental and heritage areas.



Name:	Payment Advice (North)
Reference No.:	109
Length (m):	184.01
Average Width (m):	1
Condition:	Medium
Level of Usage:	High
Predominant Usage Type:	Running/Walking
Potential to Harm Heritage or Environmental Features:	Harm likely
Required by City:	No
Recommendation:	Close. Intersects with the Tuart woodland TEC and adjacent to the Honeymyrtle shrublands TEC. Medium condition trail with the potential to facilitate weed spread and erosion effects into environmental and heritage areas.



Name:	Additional Trail 16
Reference No.:	110
Length (m):	67.84
Average Width (m):	1
Condition:	Medium
Level of Usage:	High
Predominant Usage Type:	Running/Walking
Potential to Harm Heritage or Environmental Features:	Harm likely
Required by City:	-
Recommendation:	Close. Intersects with the Tuart woodland TEC and adjacent to the Honeymyrtle shrublands TEC. Medium condition trail with the potential to facilitate weed spread and erosion effects into environmental and heritage areas.



Name:	Quarry Track 2
Reference No.:	111
Length (m):	81.58
Average Width (m):	1
Condition:	Poor
Level of Usage:	Low
Predominant Usage Type:	Mixed Use
Potential to Harm Heritage or Environmental Features:	Harm observed
Required by City:	No
Recommendation:	Close. Unauthorised mountain bike circuit including bike jumps. Erosion, trampling and weeds present. Intersects with Honeymyrtle shrublands TEC and Tuart woodlands TEC. Overgrown vegetation in sections. Poor condition trail. Not well used. Dangerous rocky sections of trail.



Name:	North
Reference No.:	112
Length (m):	184.34
Average Width (m):	1
Condition:	Poor
Level of Usage:	Low
Predominant Usage Type:	Mixed Use
Potential to Harm Heritage or Environmental Features:	Harm observed
Required by City:	No
Recommendation:	Close. Unauthorised mountain bike circuit including bike jumps. Erosion, trampling and weeds present. Intersects with Honeymyrtle shrublands TEC and Tuart woodlands TEC. Overgrown vegetation in sections. Poor condition trail. Not well used. Dangerous rocky sections of trail.



Name:	North 2
Reference No.:	113
Length (m):	175.11
Average Width (m):	1
Condition:	Poor
Level of Usage:	Low
Predominant Usage Type:	Mixed Use
Potential to Harm Heritage or Environmental Features:	Harm observed
Required by City:	No
Recommendation:	Close. Unauthorised mountain bike circuit including bike jumps. Erosion, trampling and weeds present. Intersects with Honeymyrtle shrublands TEC and Tuart woodlands TEC. Overgrown vegetation in sections. Poor condition trail. Not well used. Dangerous rocky sections of trail.



Name:	North 3
Reference No.:	114
Length (m):	123.35
Average Width (m):	1
Condition:	Poor
Level of Usage:	Low
Predominant Usage Type:	Mixed Use
Potential to Harm Heritage or Environmental Features:	Harm observed
Required by City:	No
Recommendation:	Close. Unauthorised mountain bike circuit including bike jumps. Erosion, trampling and weeds present. Intersects with Honeymyrtle shrublands TEC and Tuart woodlands TEC. Overgrown vegetation in sections. Poor condition trail. Not well used. Dangerous rocky sections of trail.



Name:	North 4
Reference No.:	115
Length (m):	36.38
Average Width (m):	1
Condition:	Poor
Level of Usage:	Low
Predominant Usage Type:	Mixed Use
Potential to Harm Heritage or Environmental Features:	Harm observed
Required by City:	No
Recommendation:	Close. Unauthorised mountain bike circuit including bike jumps. Erosion, trampling and weeds present. Intersects with Honeymyrtle shrublands TEC and Tuart woodlands TEC. Overgrown vegetation in sections. Poor condition trail. Not well used. Dangerous rocky sections of trail.



Name:	Track 2
Reference No.:	116
Length (m):	58.42
Average Width (m):	1
Condition:	Poor
Level of Usage:	Low
Predominant Usage Type:	Mixed Use
Potential to Harm Heritage or Environmental Features:	Harm observed
Required by City:	No
Recommendation:	Close. Unauthorised mountain bike circuit including bike jumps. Erosion, trampling and weeds present. Intersects with Honeymyrtle shrublands TEC and Tuart woodlands TEC. Overgrown vegetation in sections. Poor condition trail. Not well used. Dangerous rocky sections of trail.



Name:	Quarry Ascender
Reference No.:	117
Length (m):	51.19
Average Width (m):	1
Condition:	Poor
Level of Usage:	Low
Predominant Usage Type:	Mixed Use
Potential to Harm Heritage or Environmental Features:	Harm observed
Required by City:	No
Recommendation:	Close. Unauthorised mountain bike circuit including bike jumps. Erosion, trampling and weeds present. Intersects with Honeymyrtle shrublands TEC and Tuart woodlands TEC. Overgrown vegetation in sections. Poor condition trail. Not well used. Dangerous rocky sections of trail.



Name:	West Out
Reference No.:	118
Length (m):	63.41
Average Width (m):	1
Condition:	Poor
Level of Usage:	Low
Predominant Usage Type:	Mixed Use
Potential to Harm Heritage or Environmental Features:	Harm observed
Required by City:	No
Recommendation:	Close. Unauthorised mountain bike circuit including bike jumps. Erosion, trampling and weeds present. Intersects with Honeymyrtle shrublands TEC and Tuart woodlands TEC. Overgrown vegetation in sections. Poor condition trail. Not well used. Dangerous rocky sections of trail.



Name:	Additional Trail 25
Reference No.:	119
Length (m):	196.55
Average Width (m):	1
Condition:	Poor
Level of Usage:	Low
Predominant Usage Type:	Mixed Use
Potential to Harm Heritage or Environmental Features:	Harm observed
Required by City:	No
Recommendation:	Close. Unauthorised mountain bike circuit including bike jumps. Erosion, trampling and weeds present. Intersects with Honeymyrtle shrublands TEC and Tuart woodlands TEC. Overgrown vegetation in sections. Poor condition trail. Not well used. Dangerous rocky sections of trail.



Name:	Additional Trail 26
Reference No.:	120
Length (m):	293.23
Average Width (m):	1
Condition:	Poor
Level of Usage:	Low
Predominant Usage Type:	Mixed Use
Potential to Harm Heritage or Environmental Features:	Harm observed
Required by City:	No
Recommendation:	Close. Unauthorised mountain bike circuit including bike jumps. Erosion, trampling and weeds present. Intersects with Honeymyrtle shrublands TEC and Tuart woodlands TEC. Overgrown vegetation in sections. Poor condition trail. Not well used. Dangerous rocky sections of trail.



Name:	South 2
Reference No.:	121
Length (m):	63.13
Average Width (m):	3
Condition:	Good
Level of Usage:	High
Predominant Usage Type:	Running/Walking
Potential to Harm Heritage or Environmental Features:	Harm unlikely
Required by City:	Yes
Recommendation:	Keep open - maintenance. Trail overgrown in sections, may require minor vegetation trimming. Formalisation recommended in trampled sections.



Name:	Additional Trail 5
Reference No.:	122
Length (m):	118.57
Average Width (m):	2.5
Condition:	Medium
Level of Usage:	High
Predominant Usage Type:	Running/Walking
Potential to Harm Heritage or Environmental Features:	Harm likely
Required by City:	-
Recommendation:	Close. High risk of harm to the environment through continued use of the trail.



Name:	Track 1
Reference No.:	123
Length (m):	149.4
Average Width (m):	2
Condition:	Medium
Level of Usage:	High
Predominant Usage Type:	Mixed Use
Potential to Harm Heritage or Environmental Features:	Harm observed
Required by City:	No
Recommendation:	Close. Currently erosion and bike jumps present. Risk of erosion to adjacent Honeymyrtle shrubland TEC.



Name:	North Entry
Reference No.:	124
Length (m):	134.63
Average Width (m):	3
Condition:	Medium
Level of Usage:	High
Predominant Usage Type:	Running/Walking
Potential to Harm Heritage or Environmental Features:	Harm unlikely
Required by City:	No. Required by DFES.
Recommendation:	Keep open.



Name:	East
Reference No.:	125
Length (m):	329.35
Average Width (m):	3
Condition:	Medium
Level of Usage:	High
Predominant Usage Type:	Running/Walking
Potential to Harm Heritage or Environmental Features:	Harm unlikely
Required by City:	Yes
Recommendation:	Keep open.



Name:	East 1
Reference No.:	126
Length (m):	288.38
Average Width (m):	3
Condition:	Medium
Level of Usage:	High
Predominant Usage Type:	Running/Walking
Potential to Harm Heritage or Environmental Features:	Harm unlikely
Required by City:	Yes
Recommendation:	Keep open.

