

Name:	Additional Trail 9
Reference No.:	41
Length (m):	17.79
Average Width (m):	0.4
Condition:	Poor
Level of Usage:	High
Predominant Usage Type:	Mixed Use
Potential to Harm Heritage or Environmental Features:	Harm likely
Required by City:	-
Recommendation:	Keep open - Formalise. Potential for erosion to occur. Gate 12 is inaccessible by bicycles, with no other suitable access point along the western portion of Spearwood Avenue. Recommendations include formalisation to allow bicycles access off Spearwood Avenue, and to mitigate erosion risk. If the City wishes to close this trail it is recommended to modify gate 12 to allow bicycle access into Manning Park from Spearwood Avenue.



Name:	Additional Trail 10
Reference No.:	42
Length (m):	21.32
Average Width (m):	0.4
Condition:	Poor
Level of Usage:	Medium
Predominant Usage Type:	Mixed Use
Potential to Harm Heritage or Environmental Features:	Harm likely
Required by City:	-
Recommendation:	Close. Second point of access for bicycles off Spearwood Avenue. Not required if trail 41 remains open, or gate 12 is modified. Potential for erosion to occur.



Name:	Additional Trail 11
Reference No.:	43
Length (m):	155.58
Average Width (m):	2
Condition:	Medium
Level of Usage:	High
Predominant Usage Type:	Running/Walking
Potential to Harm Heritage or Environmental Features:	Harm likely.
Required by City:	-
Recommendation:	Close. Potential to cause weed spread through Tuart woodlands TEC, Northern Spearwood shrublands PEC and revegetated areas. Is not required for trail connectivity.



Name:	Azelia Hustle
Reference No.:	44
Length (m):	212.28
Average Width (m):	1
Condition:	Medium
Level of Usage:	Medium
Predominant Usage Type:	Mixed Use
Potential to Harm Heritage or Environmental Features:	Harm likely
Required by City:	No
Recommendation:	Close. Is not required for trail connectivity, forms a loop off trail 3. Intersects with revegetation area, Northern Spearwood shrublands PEC and Tuart woodlands TEC. Potential to spread weeds into revegetated area, Tuart woodlands TEC and Northern Spearwood shrublands PEC.



Name:	Get Schwifty
Reference No.:	45
Length (m):	185.69
Average Width (m):	1
Condition:	Medium
Level of Usage:	Medium
Predominant Usage Type:	Running/Walking
Potential to Harm Heritage or Environmental Features:	Harm likely
Required by City:	No
Recommendation:	Close. Intersects with Tuart woodlands TEC, Northern Spearwood shrublands PEC and revegetation area. Potential to spread weeds into all three areas. Connect trails 3 and 7. Not required for connectivity as trails 6 also connects trails 3 and 7. Not a frequently used trail.



Name:	Azelia Hustle
Reference No.:	46
Length (m):	43.47
Average Width (m):	1
Condition:	Medium
Level of Usage:	High
Predominant Usage Type:	Biking
Potential to Harm Heritage or Environmental Features:	Harm likely
Required by City:	No
Recommendation:	Close. Not required, leads to other trails to be closed. Close to avoid dead ends. Intersects with revegetation area and Northern Spearwood shrublands PEC and has the potential to introduce weeds.



Name:	Alt Route
Reference No.:	47
Length (m):	555.31
Average Width (m):	1
Condition:	Poor
Level of Usage:	High
Predominant Usage Type:	Mixed Use
Potential to Harm Heritage or Environmental Features:	Harm observed
Required by City:	No
Recommendation:	Close. Currently spreading weeds into adjacent vegetation. Risk of erosion. Intersects with Honeymyrtle shrubland TEC and Northern Spearwood shrubland PEC. Intersects with Davilak Ruins.



Name:	Get Schwifty
Reference No.:	48
Length (m):	175.93
Average Width (m):	0.3
Condition:	Poor
Level of Usage:	Low
Predominant Usage Type:	Running/Walking
Potential to Harm Heritage or Environmental Features:	Harm observed
Required by City:	No
Recommendation:	Close. Poor condition trail not frequently used. Vegetation trampling occurring.




Name:	Get Swifty
Reference No.:	49
Length (m):	410.7
Average Width (m):	1
Condition:	Poor
Level of Usage:	Medium
Predominant Usage Type:	Running/Walking
Potential to Harm Heritage or Environmental Features:	Harm observed
Required by City:	No
Recommendation:	Close. Unnecessary shortcuts. Intersect with the Northern Spearwood shrublands PEC. Risk of erosion moving into surrounding vegetation. Leads to Davilak Ruins.



Name:	Castle Face
Reference No.:	50
Length (m):	295.25
Average Width (m):	0.5
Condition:	Poor
Level of Usage:	Medium
Predominant Usage Type:	Running/Walking
Potential to Harm Heritage or Environmental Features:	Harm observed
Required by City:	No
Recommendation:	Close. Rubbish along the trail. Leads to Davilak Ruins. Trail is not necessary as it is parallel to trail 10. Not a high frequency use trail.



Name:	Additional Trail 12
Reference No.:	51
Length (m):	403.85
Average Width (m):	1
Condition:	Poor
Level of Usage:	High
Predominant Usage Type:	Running/Walking
Potential to Harm Heritage or Environmental Features:	Harm observed
Required by City:	-
Recommendation:	Close. Erosion present. Trail not necessary, links trails 5, 9 and 12. Trails 5, 9 and 12 are already linked. Poor condition trail would require significant inputs from the City to formalise.



Name:	Jack the Ripper
Reference No.:	52
Length (m):	171.91
Average Width (m):	0.5
Condition:	Poor
Level of Usage:	High
Predominant Usage Type:	Mixed Use
Potential to Harm Heritage or Environmental Features:	Harm likely
Required by City:	No
Recommendation:	Close. Unnecessary shortcut through trail 10. Has the potential to negatively affect nearby priority flora. Poor condition trail.



Name:	Switchback Singletrack
Reference No.:	53
Length (m):	220.56
Average Width (m):	0.5
Condition:	Poor
Level of Usage:	High
Predominant Usage Type:	Mixed Use
Potential to Harm Heritage or Environmental Features:	Harm Likely
Required by City:	No
Recommendation:	Close. Unnecessary shortcut between trails 10 and 11. Potential to introduce weeds and erosion effects into the adjacent Honeymyrtle shrublands TEC.



Name:	Additional Trail 13
Reference No.:	54
Length (m):	13.62
Average Width (m):	0.3
Condition:	Poor
Level of Usage:	Medium
Predominant Usage Type:	Running/Walking
Potential to Harm Heritage or Environmental Features:	Harm likely
Required by City:	-
Recommendation:	Close. Unauthorised shortcut trail connecting trails 10 and 82. Potential to facilitate weed spread throughout the park. Poor condition trail and not highly frequented.



Name:	Duck
Reference No.:	55
Length (m):	219.45
Average Width (m):	1
Condition:	Medium
Level of Usage:	Medium
Predominant Usage Type:	Running/Walking
Potential to Harm Heritage or Environmental Features:	Harm likely
Required by City:	No
Recommendation:	Close. Potential to facilitate weed spread through Honeymyrtle shrublands TEC, Tuart woodlands TEC and revegetation areas. Not frequently used.



Name:	Additional Trail 14
Reference No.:	56
Length (m):	39.84
Average Width (m):	0.5
Condition:	Poor
Level of Usage:	Medium
Predominant Usage Type:	Running/Walking
Potential to Harm Heritage or Environmental Features:	Harm unlikely
Required by City:	-
Recommendation:	Close. Unnecessary shortcut between trail 82 and 85. Poor condition trail, not frequently used.



Name:	Additional Trail 15
Reference No.:	57
Length (m):	179.41
Average Width (m):	0.3
Condition:	Poor
Level of Usage:	Low
Predominant Usage Type:	Running/Walking
Potential to Harm Heritage or Environmental Features:	Harm observed
Required by City:	-
Recommendation:	Close. Intersects with Tuart woodland TEC and revegetation area. Trampling effects present. Poor condition trail not frequently used. Does not connect with the existing Manning Park trails network.



Name:	Firebreak 1
Reference No.:	58
Length (m):	701.67
Average Width (m):	0.5
Condition:	Poor
Level of Usage:	Low
Predominant Usage Type:	Running/Walking
Potential to Harm Heritage or Environmental Features:	Harm observed
Required by City:	No
Recommendation:	Close. Trail is currently facilitating weed spread. Trampling effects present on existing vegetation. Meandering trail off trail 13. Connects to a trail recommended for closure (29).



Name:	South 2
Reference No.:	59
Length (m):	126.90
Average Width (m):	1
Condition:	Medium
Level of Usage:	High
Predominant Usage Type:	Running/Walking
Potential to Harm Heritage or Environmental Features:	Harm likely
Required by City:	No
Recommendation:	Close. Intersects with the Tuart woodland TEC and adjacent to the Honeymyrtle shrublands TEC. Medium condition trail with the potential to facilitate weed spread and erosion effects into environmental and heritage areas.



Name:	Payment Advice (South)
Reference No.:	60
Length (m):	162.88
Average Width (m):	0.5
Condition:	Poor
Level of Usage:	Medium
Predominant Usage Type:	Running/Walking
Potential to Harm Heritage or Environmental Features:	Harm likely
Required by City:	No
Recommendation:	Close. [REDACTED] Honeymyrtle shrublands TEC. Potential to spread weeds and erosion effects to nearby features. Connects two trails recommended to close (30 and 107). Poor condition trail that is not well used.

